

# Capital Facility Needs – Metea Feeder (10-Year Needs Assessment)

	Brookdale	Brooks	Cowlishaw	Longwood	Owen	Watts	Young	Granger	Hill	Metea
<b>✓ SAFETY AND SECURITY</b>										
Vestibule Improvements, Line of Sight, Main Office Configuration	●	●	●	●	●	●	●	●	●	●
Fire Protection System (Sprinklers)	●			●		●		●	●	
Systems (Access Controls, Security Cameras, Other)	●	●	●	●	●	●	●	●	●	●
<b>✓ INFRASTRUCTURE - SYSTEMS</b>										
Electrical Upgrades	●	●	●	●	●	●	●	●	●	
Technology/Low Voltage System Upgrades	●	●	●	●	●	●	●	●	●	
Partial Roofing Replacement	●		●	●			●	●	●	
Exterior Wall Repairs	●								●	
Window Replacement	●	●	●	●	●	●	●	●	●	
Asphalt Parking Lot and Sidewalk Improvements		●		●			●		●	
<b>✓ INFRASTRUCTURE – LEARNING ENVIRONMENTS</b>										
HVAC Upgrades/Air Quality Improvements	●	●	●	●	●	●	●	●	●	
Energy Efficient LED Lighting	●	●	●	●	●	●	●	●	●	●
Wall, Ceilings, and Floor Finishes	●	●	●	●	●	●	●	●	●	
Furniture	●	●	●	●	●	●	●	●	●	●
<b>✓ COMPREHENSIVE IMPROVEMENTS</b>										
Phased additional and comprehensive renovations (including all items above) due to the age, size, and complexity of individual school sites									●	



# Capital Facility Needs – Neuqua Feeder (10-Year Needs Assessment)

	Buila	Clow	Graham	Kendall	Patterson	Spring Brook	Welch	Crone	Gregory	Birkett	Neuqua
<b>✓ SAFETY AND SECURITY</b>											
Vestibule Improvements, Line of Sight, Main Office Configuration	●	●	●	●	●	●	●	●	●	●	●
Fire Protection System (Sprinklers)		●				●		●	●	●	●
Systems (Access Controls, Security Cameras, Other)	●	●	●	●	●	●	●	●	●	●	●
<b>✓ INFRASTRUCTURE - SYSTEMS</b>											
Electrical Upgrades	●	●	●	●	●	●	●	●	●	●	●
Technology/Low Voltage System Upgrades	●	●	●	●	●	●	●	●	●	●	●
Partial Roofing Replacement							●	●	●	●	●
Exterior Wall Repairs								●	●	●	●
Window Replacement	●	●	●	●	●	●	●	●	●	●	●
Asphalt Parking Lot and Sidewalk Improvements	●	●	●	●	●		●	●	●		●
<b>✓ INFRASTRUCTURE – LEARNING ENVIRONMENTS</b>											
HVAC Upgrades/Air Quality Improvements	●	●	●	●	●	●	●	●	●	●	●
Energy Efficient LED Lighting	●	●	●	●	●	●	●	●	●	●	●
Wall, Ceilings, and Floor Finishes	●	●	●	●	●	●	●	●	●	●	●
Furniture	●	●	●	●	●	●	●	●	●	●	●
<b>✓ COMPREHENSIVE IMPROVEMENTS</b>											
Phased additional and comprehensive renovations (including all items above) due to the age, size, and complexity of individual school sites									●		●



# Capital Facility Needs – Waubonsie Feeder (10-Year Needs Assessment)

	Fry	Georgetown	Gombert	McCarty	Peterson	Steck	White Eagle	Fischer	Scullen	Still	Waubonsie
<b>✓ SAFETY AND SECURITY</b>											
Vestibule Improvements, Line of Sight, Main Office Configuration	●	●	●	●	●	●	●	●	●	●	●
Fire Protection System (Sprinklers)		●		●				●	●	●	●
Systems (Access Controls, Security Cameras, Other)	●	●	●	●	●	●	●	●	●	●	●
<b>✓ INFRASTRUCTURE - SYSTEMS</b>											
Electrical Upgrades	●	●	●	●	●	●	●	●	●	●	●
Technology/Low Voltage System Upgrades	●	●	●	●	●	●	●	●	●	●	●
Partial Roofing Replacement		●				●		●	●	●	●
Exterior Wall Repairs	●	●								●	●
Window Replacement	●	●	●	●	●	●	●	●	●	●	●
Asphalt Parking Lot and Sidewalk Improvements	●	●		●		●	●	●		●	●
<b>✓ INFRASTRUCTURE – LEARNING ENVIRONMENTS</b>											
HVAC Upgrades/Air Quality Improvements	●	●	●	●	●	●	●	●	●	●	●
Energy Efficient LED Lighting	●	●	●	●	●	●	●	●	●	●	●
Wall, Ceilings, and Floor Finishes	●	●	●	●	●	●	●	●	●	●	●
Furniture	●	●	●	●	●	●	●	●	●	●	●
<b>✓ COMPREHENSIVE IMPROVEMENTS</b>											
Phased additional and comprehensive renovations (including all items above) due to the age, size, and complexity of individual school sites											●

